




1088

TRAILER-BRITE

SPECIALTIES FOR MAINTENANCE AND SANITATION SINCE 1947

Makes Your Rig **The Envy** of the **Interstate**



REMOVES:

- ROAD FILM
- SMOKE
- OXIDATION
- CORROSION

Especially Formulated to Clean and **Brighten**

- ACTIVATED ACID
- FREE RINSING
- SPRAY OR MANUAL APPLICATION WITH HOT OR COLD WATER
- KEEPS YOUR MOBILE ADVERTISEMENT BEAUTIFUL AND ATTRACTIVE
- INCREASES SERVICE LIFE AND EQUIPMENT VALUE



Packaged in 55 Gallon Drums

Rev. 5-3-11

Toll Free: 800-238-5150
Local: 901-363-4340
Fax: 901-375-3600

Delta Foremost Chemical Corp.
3915 AIR PARK ST. • P.O. BOX 30310 • MEMPHIS, TN 38130-0310

Visit our Web Site at:
www.deltaforemost.com



TECHNICAL DATA

FOREMOST 1088 TRAILER BRITE

Rev. 5-3-11

DESCRIPTION: A highly concentrated solution of acid with selected additives and detergent, which is non-flammable and emits no toxic odors. It is completely soluble in water, rinses thoroughly leaving no streaks or residue. It has been especially formulated for heavy duty cleaning and removal of oxidation deposits from aluminum and other surfaces.

APPLICATION: Recommended for cleaning and removal of road and oxide films and deposits from aluminum surfaces such as trailers and similar surfaces. When used as directed, diluted solutions will not harm aluminum, painted surfaces, signs or decals.

DIRECTIONS: **FOR SPRAY WASHING OR MANUAL BRUSHING:**

1. For heavy oxidation and diesel smoke use 1 part Foremost 1088 to 10 to 20 parts cold water or 1 part to 30 to 40 parts hot water. For light contamination use part Foremost 1088 to 20 to 40 parts cold water or 1 part to 50 to 60 parts hot water.
2. Work from bottom surface upward, an area at a time.
3. Allow solution to remain on surface approximately 3 to 5 minutes, then rinse thoroughly.

NOTE: Contains hydrofluoric acid. Do not allow concentrate or use solution to contact glass. Heated solutions increase the speed and effectiveness of Trailer Brite.

PRECAUTIONS: **KEEP OUT OF REACH OF CHILDREN.** Contains hydrofluoric acid and phosphoric acid. Causes severe eye and skin burns. Do not get in eyes, on skin, or clothing. Causes severe respiratory tract irritation. Do not breathe vapors. Vapor extremely irritating. Use with adequate ventilation. Do not take internally. When handling always wear chemical splash goggles, face shield, rubber gloves and protective clothing.

FIRST AID: EYES AND SKIN: In case of contact, immediately flush with plenty of water for at least 15 minutes. Remove contaminated clothing and shoes under shower. Get medical attention immediately. **INGESTION:** If conscious, give large amounts of lime water or milk of magnesia or water. Get medical attention immediately. **INHALATION:** If affected, move to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Get medical attention immediately.

Before using this product, read the Material Safety Data Sheet (MSDS) for more detailed information regarding safe handling.

FACTS

1. Fast
2. Protects
3. Economical
4. Simple to use

BENEFITS

1. Speedy penetration of stubborn deposits
2. Buffered Acidity
3. Can be diluted up to 80 to 1
4. No special equipment needed.